



ASQ CRE Prep course

Lesson I. A. 8.

Supplier Reliability

An aerial photograph of Paris, France, taken during the 'golden hour' of sunrise or sunset. The sun is a large, bright orb in the upper center of the frame, casting a warm, golden glow over the city. The sky is filled with soft, white clouds. In the foreground and middle ground, the dense urban landscape of Paris is visible, with numerous buildings, streets, and trees. The Eiffel Tower stands prominently on the right side of the image. The overall atmosphere is serene and majestic.

How reliability is the stuff we buy to create our product

SUPPLIER RELIABILITY

Key Steps for Supplier Reliability

- **Document basic supplier requirements**
- **Analyze supplier capabilities**
- **Review proposal for detail on conformance**
- **Consider a number of factors (TQRDCe)**

Key Steps for Supplier Reliability

- **Work together to finalize criteria**
- **Monitor process (SPC)**
- **Check process capability**
- **Demonstration testing**

Key Steps for Supplier Reliability

- **Provide feedback to supplier**
- **FRACAS system (CAPA)**
- **Program & Project reviews**
- **Long term testing**

Partners?



ASQ CRE Prep course

Lesson I. B.

Reliability Program
Management



Work the Quizzes

Take the Sample Exam

Send over your questions

Participate in class forum